

Oil Field Environmental Incident Summary

Incident: 20150409175434 **Date/Time of Notice:** 04/09/2015 17:54
Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: CCU FOUR ACES CTB
Field Name: CORRAL CREEK **Well File #:**
Date Incident: 4/9/2015 **Time Incident:** 08:00 **Facility ID Number:** 416647-07
County: WILLIAMS **Twp:** 147 **Rng:** 95 **Sec:** 21 **Qtr:** SE SW
Location Description: off of the east side of the central tank battery

Submitted By: Lewis Schoenberger **Received By:**
Contact Person: Lewis Schoenberger
PO BOX 51810
MIDLAND, TX 79710-1810

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 1.5 Mile
Distance Nearest Water Well: 1.5 Mile

Type of Incident: Other

Release Contained in Dike: No **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.5	Barrels				
Brine						
Other						

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 8/3/2016 **Clean Up Concluded:** 4/16/2015
Risk Evaluation:
None

Areal Extent:
approximately 600 feet by 60 feet.

Potential Environmental Impacts:

None

Action Taken or Planned:

Oil impacted vegetation will be collected for appropriate disposal.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 4/10/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted area off location according to report. Followup is required.

Date: 4/15/2015 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 4/15/2015, at 1:15 p.m. Impacted area off site is pasture land to the east of well pad. Impacted area is approximately 700 X 90 ft. Area has been mowed down, and cut vegetation has been removed. There is still impact seen at this time to vegetation. Soil samples were taken. I also spoke with company contact about taking confirmation samples. More followup may be required depending on sample results. Note that location is in Dunn County, not Williams County as listed on incident summary.